




























Annex F Laboratory Signage

Personal Protection & Other Safety Requirements Postings for Laboratories & Other Areas			
Requirement	Symbol	Requirement	Symbol
No Open Toe Shoes		No Pacemakers in this Area	
No Eating Allowed		Wear Face Shield	
Lab Safety Glasses Required		Wear Hearing Protection	
Lab Coat Required		Wear Gloves	

Hazardous Materials /Processes Signage			
HAZMAT Element	Symbol	HAZMAT Element	Symbol
1 Class 1 Explosives		11 Class 5.2 Organic Peroxide	
2 Class 2.1 Flammable Gas		12 Class 6.1 Solid or Liquid that is toxic	
3 Class 2.2 Non-flammable, Non-toxic Gas		13 Class 6.2 Infectious Microorganisms (BL-01)	
4 Class 2.2 (5.1) Oxygen and Oxidizing Gas		14 Class 6.2 Infectious Microorganisms (BL-02)	

Hazardous Materials /Processes Signage			
HAZMAT Element	Symbol	HAZMAT Element	Symbol
5 Class 2.3 Toxic Gas		15 Class 6.2 Infectious Microorganisms (BL-03)	
6 Class 3 Flammable Liquids		16 Radioactive Material	
7 Class 4.1 Flammable Solids		17 Class 8 Corrosive Material	
8 Class 4.2 Spontaneously Combustible		18 Laser	
9 Class 4.3 Dangerous when wet		19 High Energy Magnet Laser	
10 Class 5.1 Oxidizer		20 X-Ray	